YAESU
The radio

3/13/26

FTX-1 Firmware Update Information

Download the FTX-1 [**FTX-1_ENG_Firmware_Update_202603.zip**] from the following website: https://www.yaesu.com/product-detail.aspx?Model=FTX-1%20Series&CatName=HF%20Transceivers/Amplifiers

[FTX-1_Firmware_update_**202603**]zip Contains:

・ **DISPLAY** : **FTX-1_DISPLAY_V0109.SFL** (New)

・ **MAIN** : **FTX-1_MAIN_V0111.SFL** (New)

・ **DSP** : **FTX-1_IFDSP_V0107.SFL** (New)

・ **SDR** : **FTX-1_SDR_V0106SFL** (New)

・ **OPT** : **SPA-1_CTRL_V0113.SFL**

   <u>**(FTX-1)**</u>

- **DISPLAY** **V01-07 → V01-09**
- **MAIN** **V01-10 → V01-11**
- **DSP** **V01-05 → V01-07**
- **SDR** **V01-05 → V01-06**

   <u>**(SPA-1)**</u>

- **OPT** **V01-13 → V01-13**

**Important: Please read the FTX-1 series Firmware Upgrade Manual,
Firmware_Ver_Up_Manual_ENG_FTX-1_2603A.pdf**

Update Details (Web Release) (March 2026)

・WIRES-X Support Added

・Resolved an issue preventing manual tuning in CW mode when using the ATAS-120.

・Resolved a bug where the UPPER/LOWER display on the Scope would invert during SSB transmission on the 50 MHz band.

・Other minor fixes.

Note: After completely installing the firmware, the FTX-1 must be reset.
Refer to the FTX-1 series Operating Manual Page 79.
Or refer to the **Firmware_Ver_Up_Manual_ENG_FTX-1_2603A.pdf**

Reset the transceiver

1. Turn the transceiver OFF.
2. While pressing the [**BACK**] and [**FINE/FAST**] keys simultaneously, then turn the transceiver **ON**.
   - The frequency display will return to "144.000.000" (SUB-side), "7.000.000" (MAIN-side).

This completes the firmware upgrading process.

If you already have the above firmware versions, it is not necessary to update the FTX-1 again.

We hope this new firmware will increase your enjoyment of your FTX-1. Thank you for choosing Yaesu radios. If you have any problems or questions, please contact Yaesu Amateur Tech Support amateurtech@yaesu.com.