



11/08/17 (Rev 1)

FTM-3200DR/DE Firmware Update Information

Refer to the Firmware Update Instruction Manual in each ZIP file.

The latest versions are listed below with the release dates.

- MAIN Firmware Version **2.11** (11/08/17)
- DSP Firmware Version **4.15** (09/08/17)

Currently we have two different destination versions of the FTM-3200DR/DE: USA (including AUS) and EXP (including EU and CHN). The Main and DSP Update Firmware covers all countries (two different destinations).

Please open the Update Instruction Manual and review the information before starting the update firmware.

Download the FTM-3200DR/DE data and [FTM-3200D_Firmware_Update_1114.zip] from the website listed below.

<http://yaesu.com/indexVS.cfm?cmd=DisplayProducts&ProdCatID=249&encProdID=1C299659CDFD4B56DDBBA4BA23026510&DivisionID=65&isArchived=0>

MAIN (covers all countries)

Folder Name: FTM-3200D_ver211

DSP (covers all countries)

Folder Name: PCTOOLe_v0415.zip

The update zip file contains DSP firmware [PCTOOLe_v0415.zip] it is for all countries.

CAUTION:

Please be sure to confirm the model and the version of your transceiver before starting the update. Writing incorrect firmware to the transceiver may cause abnormal operation or failure.

Please read the FTM-3200DR/DE Firmware Upgrade Manual before proceeding!

Implements improvements

FTM-3200DR/DE Main Version 2.11 (11/08/17)

DSP PCTOOLe Version 4.15 (09/08/17)

- The WIRES-X connection function is added.
- Added the DG-ID setting for the WIRES-X node station connection to the set mode menu (Set Mode: 50: W-DGID).

By adding DG-ID function, the group settings which were difficult are made easy.

NOTE:

- After updating this firmware, please note that the group function cannot be used with the C4FM digital transceiver which has not been updated.
- The set mode will be initialized, so please make your personal settings again after the update.
- After updating the firmware, the clone operation cannot be performed with a transceiver that has not been updated. After updating, the clone operation is effective only between transceivers that have the updated firmware.

When MAIN Firmware V2.11 is installed you must check the DSP PCTOOLe Version 4.15. If you do not have V4.15 DSP Firmware, then it must also be installed at the same time (otherwise it may not function correctly).

If you already have the above listed firmware versions, it is not necessary to update the FTM-3200DR/DE again.

We hope this new Firmware will increase your enjoyment of the FTM-3200DR/DE. Thank you for choosing Yaesu radios. If you have any problems or questions please contact Yaesu Amateur Tech Support amateurtech@yaesu.com.