



6/15/17

FT-891 Firmware Update and Version Identification

The latest versions are listed below with the release dates.

- MAIN Firmware Version **01-06** (6/15/17)

*If you already have MAIN: Ver. **01-06** firmware versions, it is not necessary to update the FT-891 again.

There are three different firmware installations. Each one must be followed carefully. Installing the wrong type firmware may cause difficulties. Check your radio before installing firmware to be sure which updates are needed. **Please read the FT-891 Firmware Upgrade Manual before proceeding.**

Before installing new firmware, please verify your current version firmware with the following procedure:

How to Confirm the Current Firmware Version of the transceiver

MAIN, DSP, and LCD(Panel) firmware are available for FT-891 transceiver. Check the firmware version, and perform firmware updates when needed.

1. Press and hold the [PWR/LOCK] key to turn the transceiver ON.
2. Press and hold the [F] key to activate the Menu mode.
3. Rotate the MULTI function knob to select Menu Mode "18-01 [MAIN VERSION]", "18-02 [DSP VERSION]" or "18-03 [LCD VERSION]".

The firmware versions will be displayed on the LCD screen.



(This image & version is for illustration only)

Download the FT-891 data and [**FT-891_Main_V0106.zip**] from the following website:

<http://www.yaesu.com/indexVS.cfm?cmd=DisplayProducts&ProdCatID=102&encProdID=D24F60F33816ED8BE5568D7E2B5E2131&DivisionID=65&isArchived=0>

Please read the FT-891 Firmware Upgrade Manual before proceeding!

MAIN Firmware Ver. 01-06 (6/15/17)

- Corrected the automatic power ON when reset operation by Menu mode or the CAT command.
- Corrected the memory tag reading/note (lower case letters) by the CAT command.

We hope this new firmware will increase your enjoyment of your FT-891. Thank you for choosing Yaesu radios. If you have any problems or questions, please contact Yaesu, Amateur Tech Support amateurtech@yaesu.com.

Best regards,

Mikio Maruya, WA6F
Executive Vice President
Engineering & Customer Service
Yaesu USA