

September 23, 2016

Latest Firmware Update for the DR-1X Repeater

Dear DR-1X Operators;


Thank you for your patronage of YAESU products.

Please be informed that we released the latest firmware updates for the DR-1X Repeater.

Before installing the new firmware, please determine the appropriate firmware version for your DR-1X. There are three different firmware versions depending on marketing regions.

To check the firmware version of your DR-1X Repeater;

- 1. Turn Power ON
- 2. Press "SET UP" Button on the Operation Mode Screen
- 3. The current Firmware Version is displayed at the top of the Screen



Please use the appropriated new firmware to provide the listed functions:

- <u>V1.00n</u> Replaces any firmware versions, other than V1.10D and V1.00f. Provides **Wide-FM operation**
- V1.10Q
 Replaces V1.10J or V1.10D.

 Provides Selectable Wide/*Narrow-FM operation and Supports Connectivity direct to the HRI-200
- V1.00tReplaces V1.00f (If the DR-1X already has V1.00t, it does not need this update).Provides Selectable Wide/*Narrow-FM operation
(*The narrow band deviation is for some European countries.)

Thank you for your attention and continued support of YAESU.