



7/15/20

FTM-300DR/DE Firmware Update Information

Refer to the Firmware Update Instruction Manual in each ZIP file.

The latest versions are listed below with the release dates.

- MAIN Firmware Version **1.10** (7/15/20)
- DSP PCTOOLe Version **7.11** (7/15/20)

Currently we have two different destination versions of the FTM-300DR/DE: USA and EXP (including EU and CHN). Please open the Update Instruction Manual and review the information before starting the update firmware.

*The firmware version for Japan is different from USA or EXP version. Please check the latest firmware of the Japanese version on the Japan WEB site:

http://www.yaesu.com/jp/amateur_index/product/ftm-300d/download.html

You must check the destination version of the radio you have and use the correct update firmware. The destination is marked on the box serial number label. If the box is not available, the country you purchased the radio in may indicate the destination. If the FCC part 15 rules statement is on the radio above the Serial/ID label, it is the USA version. Other versions will not have the FCC label.

Download the FTM-300DR/DE data and [FTM-300D_USA_Firmware_Update_2020_07.zip] or [FTM-300D_EXP_Firmware_Update_2020_07.zip] from the website listed below.

<https://www.yaesu.com/index.VS.cfm?cmd=DisplayProducts&ProdCatID=249&encProdID=309B798AD35CA03C88C102835725005C&DivisionID=65&isArchived=0>

MAIN

- **DST: USA** version covers North and South America, Australia and New Zealand*
Folder Name: [FTM-300D_USA_Firmware_Update_2020_07.zip]

- **DST: EXP/EU/CHN** covers all other countries except USA, Australia, and New Zealand
Folder Name: [FTM-300D_EXP_Firmware_Update_2020_07.zip]

DSP (covers all countries)

Folder Name: [FTM-300D_DSP_ver0711(ENG).zip]

The updated zip file contains DSP firmware for all countries.

CAUTION:

Please be sure to confirm the model and the version of your transceiver before starting the update. Writing incorrect firmware to the transceiver may cause abnormal operation or failure.

Please read the FTM-300DR/DE Main and DSP Firmware Update Instruction Manuals before proceeding!

Implements improvements

FTM-300DR/DE Main Ver. 1.10 (7/15/20)

FTM-300DR/DE DSP PCTOOLe Ver. 7.11 (7/15/20)

- Fixed a problem that scanning freezes when executed from M-GRP, and scan settings are not set for all memory channels registered in M-GRP.
- Fixed the bug of No TX output with the MAIN Band is set to the 430 MHz band and the SUB Band set to the VHF band (144 MHz band or AIR band, etc.) if the SUB Band frequency is changed (turning the dial) during transmission in the MAIN Band.
- Improved the quality of downlink audio output in the WIRES-X Portable-HRI mode Direct operation, and the PDN (Portable Digital Node)
- Corrected the problem in WIRES-X Portable-HRI mode Direct operation. This station uplink audio was not transmitted to the Internet immediately after receiving a VW mode signal via the Internet.
- Fixed the bug that “[No Data]” pops up when playing WIRES-X Voice News
- Corrected the APRS STATION LIST detail screen. When the “F(SETUP)” key was pressed to display the function line menu in the [TOP] / [TEXT] line move selection, if the dial was turned to move the cursor while [TEXT] is displayed, the cursor could not be returned to [TEXT] entry.
- Other functions have been improved and optimized.

If you already have the above listed firmware versions, it is not necessary to update the FTM-300DR/DE again.

We hope this new firmware will increase your enjoyment of the FTM-300DR/DE. Thank you for choosing Yaesu radios. If you have any problems or questions please contact Yaesu Amateur Tech Support amateurtech@yaesu.com.