



11/1/23

## Network Remote Control System SCU-LAN10 Firmware Upgrade Information

Download the [SCU-LAN10\_Firmware\_Software.zip] from the following website:

FT-710:

<https://www.yaesu.com/indexVS.cfm?cmd=DisplayProducts&ProdCatID=102&encProdID=615ADF EAB5EDBC65EBE1D64835F209DB&DivisionID=65&isArchived=0>

FTDX10

<https://www.yaesu.com/indexVS.cfm?cmd=DisplayProducts&ProdCatID=102&encProdID=1ABBC2 3C7EC57175A35CB0FDE7A639A0&DivisionID=65&isArchived=0>

FTDX101MP:

<https://www.yaesu.com/indexVS.cfm?cmd=DisplayProducts&ProdCatID=102&encProdID=BA2F41 4449407A4D3D23461143F88429&DivisionID=65&isArchived=0>

FTDX101D:

<https://www.yaesu.com/indexVS.cfm?cmd=DisplayProducts&ProdCatID=102&encProdID=959169D E998192AB87295E90077D740D&DivisionID=65&isArchived=0>

Please read the SCU-LAN10 Firmware Upgrade Manual (2310A). Also, read the Network Remote Control System SCU-LAN10 Installation Manual (2310-C) and the Network Remote Control System SCU-LAN10 Operation Manual (2310-C). Review the information before starting the upgrade firmware.

### **SCU-LAN10 Firmware Software.zip**

Supported Models: FT-710, FTDX10, FTDX101MP & FTDX101D

**Note:** Users must install the SCU-LAN10\_Software\_V0300 (**Network Remote Control Software**) and the SCU-LAN10\_Firmware\_update\_202310 (**SCU-LAN10 Unit**) together at the same time. FT-710 users must update both, otherwise SCU-LAN10 will not work with FT-710.

### **Implements improvements:**

Major updates from V0200:

- Support for the FT-710

If you already have the above firmware version, it is not necessary to update the SCU-LAN10 again. We hope this new firmware will increase your enjoyment of your SCU-LAN10. Thank you for choosing Yaesu radios. If you have any problems or questions, please contact Yaesu Amateur Tech Support [amateurtech@yaesu.com](mailto:amateurtech@yaesu.com).